

BIJLAGE 5B: Fotoreportage ORTHOWAND 3 (wand tussen profiel 3 en profiel 1) van monitoringperiode 15/10/2015 – 17/10/2017

1: grote brok grond afgevallen/afgeschoven



15102015



15122015



15122015



16022016



17032016



12042017



21092017