


BIJLAGE 11B: Fotoreportage ORTHOWAND 9 (PROFIEL 2) van monitoringperiode 15/10/2015 – 17/10/2017

Overzicht volledige profielwand



1-6: afgevallen (of uitgegraven) schilfers en brokjes grond



12042017



21092017



15092016




08112016



21092017



17102017



28042016



28062016



28062016



08112016



15102015



15122015



17032016



08112016



27022017



17102017



17032016




17102017

7-9: dierlijke ingravenen



28062016



18102016




15122015



16052017




21092017




17102017

10: evolutie opslag abeel



28062016



16052017



31052016



16052017